



Work Order (Bid Form)

AUDITOR: J SUMMERS

615-473-2343

JSUMMERS@UNITED.NET



WORK ORDER INFORMATION

Work Order Name: WO/90009MD2665/1

Work Order Type: Weatherization

Audit Name: 90009MD2665

CLIENT INFORMATION

Client Name:

Address:

Client ID: 90009MD2665

, 37218

Alt. Client ID: DAVIDSON

AGENCY INFORMATION

Agency: Metropolitan Development and Housing Agency

Agency Phone: (615) 252-8500

Address: 701 South Sixth Street
Nashville, TN 37206

Fax: (615) 252-8533

Email Address:

Company Name & License Number: _____

Contractor's Signature: _____

COMMENT

SITEBUILT: 1972

Client Name:

Client ID: 90009MD2665

Alt. Client ID: DAVIDSON

Work Order (Bid Form)

Work Order Name: WO/90009MD2665/1

Report Run On: 4/9/2012

DOE Weatherization Assistant

Version 8.6.0

Page 1 of 5

Measures

Measure 1 Seal Ducts

Components

Inspected

Comment DUCT SEALING MEASURES:

☐

- 1.) MASTIC SEAL ALL REGISTERS, BOOTS AND JOINTS
- 2.) MASTIC SEAL RETURN INTERIOR AND EXTERIOR IN CLOSET IN BR2
- 3.) CLEAN RETURN
- 4.) INSTALL AIR FILTER, LEAVE 5 FOR CLIENT 20 X 25

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Miscellaneous Su	Duct Sealing	Each	1					

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:

Sub Total:

Field Notes:

Measure 2 Infiltration Redctn

Components

Inspected

Comment INFILTRATION REDUCTION MEASURES:

☐

- 1.) SEAL DRYER GAPS AT DRYER VENT INTERIOR AND EXTERIOR.
- 2.) DS/WS FRONT AND SIDE DOORS
- 3.) SEAL PLUMBING PENETRATIONS KITCHEN AND ONE BATH
- 4.) SEAL PLUMBING ACCESS UNDER BATH VANITY
- 5.) SEAL FRAME AROUND EXTERIOR DR1 (FRONT)
- 6.) WS ATTIC SCUTTLE

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Miscellaneous Su	Infiltration Reduction	Each	1					

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:

Sub Total:

Field Notes:

Client Name:

Client ID: 90009MD2665

Alt. Client ID: DAVIDSON

Work Order (Bid Form)

Work Order Name: WO/90009MD2665/1

Report Run On: 4/9/2012

DOE Weatherization Assistant

Version 8.6.0

Page 2 of 5

Measure 3 DWH Tank Insulation**Components****Inspected****Comment** 40 Gal Elec.☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equip	DHW Tank Insulation	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	DHW Tank Insulation	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:****Measure 4 DWH Pipe Insulation****Components****Inspected****Comment** First 5 Ft.☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	DHW Pipe Insulation	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:**

Client Name:

Client ID: 90009MD2665

Alt. Client ID: DAVIDSON

Work Order (Bid Form)

Work Order Name: WO/90009MD2665/1

Report Run On: 4/9/2012

DOE Weatherization Assistant

Version 8.6.0

Page 3 of 5

Measure 5 Floor Ins. R-19**Components** F1**Inspected****Comment** FLOOR JOISTS: 2 X 8 X 16☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Floor Insulation - Fiberglass Faced Batt - R-19	SqFt	1100	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Floor Insulation - Fiberglass Faced Batt - R-19	SqFt	1100	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:****Measure 6 Refrigerator Rplcmnt****Components****Inspected****Comment** REPLACE WITH 20 Cuf Energy Star Rated Top Freezer Unit. Remove Old Unit From Premises as Per DOE / MDHA Guidelines.☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
10	Refrigerators	any - any	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:**

Client Name:

Client ID: 90009MD2665

Alt. Client ID: DAVIDSON

Work Order (Bid Form)

Work Order Name: WO/90009MD2665/1

Report Run On: 4/9/2012

DOE Weatherization Assistant

Version 8.6.0

Page 4 of 5

Measure 7 Attic Ins. R-11**Components** A1**Inspected****Comment** ATTIC : 2 X 8 X 16 6" EXISTS, INSTALL TO R38 UP TO 16" DEPTH.☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Attic Insulation - Cellulose, Blown - R-11	SqFt	1100	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Attic Insulation - Cellulose, Blown - R-11	SqFt	1100	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:****Measure 8 Install Bathroom Exhaust Fan****Components****Inspected****Comment** INSTALL BATH EXHAUST FAN, VENT TO OUTSIDE, THRU SOFFIT OR ROOF.☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Bathroom exhaust fan	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Hour	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:****Work Order Grand Total:****Grand Total:**

Client Name:

Client ID: 90009MD2665

Alt. Client ID: DAVIDSON

Work Order (Bid Form)

Work Order Name: WO/90009MD2665/1

Report Run On: 4/9/2012

DOE Weatherization Assistant

Version 8.6.0

Page 5 of 5